

| NO. | COMPANY | BRAND NAME | PRODUCT NAME | MODEL NO./CODE | COOLING CAPACITY (KW) | POWER RATING (WATTS) | MONTHLY ESTIMATED ELECTRICITY CONSUMPTION (KWH) | ENERGY EFFICIENCY RATING (CSPP) | ENERGY EFFICIENCY PERFORMANCE RATING | Refrigerant Used | GWP | PELP PUBLIC PRODUCT LINK |
|-----|---|---------------|---|----------------------|-----------------------|----------------------|---|---------------------------------|--------------------------------------|------------------|------|---|
| 188 | Daikin Airconditioning Philippines Inc. | Daikin | SkyAir High Efficiency Inverter - Streamer Cassette | FCTF100AVM/RZF100CVM | 10 | 2970 | 400.95 | 6.45 | 5 | R32 | 675 | https://pelp.doe.gov.ph/vapproved.php?2kFrEgSb3zDqkrcjR6sZ4M3BTNvJY3NtUdV2SThXmndLCH2ZUwZ6o0 |
| 189 | Daikin Airconditioning Philippines Inc. | Daikin | SkyAir High Efficiency Inverter - Streamer Cassette | FCTF125AVM/RZF125CVM | 12.5 | 4180 | 564.3 | 5.7 | 5 | R32 | 675 | https://pelp.doe.gov.ph/vapproved.php?7v11Zk9hQzRUUMXkvZ0yQzVle9rVIEZOTZkZkG1uziFInKkHUGVITTO |
| 190 | Daikin Airconditioning Philippines Inc. | Daikin | SkyAir High Efficiency Inverter - Streamer Cassette | FCTF140AVM/RZF140CVM | 14 | 5470 | 738.45 | 5.4 | 5 | R32 | 675 | https://pelp.doe.gov.ph/vapproved.php?YndSklqzVMWTFDckVvRXNHrmiBNDZCMFvD0cvMRKZzRiXBZUTIV4o0 |
| 191 | Daikin Airconditioning Philippines Inc. | Daikin | SkyAir High Efficiency Inverter - Streamer Cassette | FCTF71AVM/RZF71CVM | 7.1 | 1930 | 260.55 | 6.4 | 5 | R32 | 675 | https://pelp.doe.gov.ph/vapproved.php?7RUnnOWIRKZuKz13MEZL3Vr2Z2eURSUgXrYnhvTXgwVW82BHE1d6k3o0 |
| 192 | Finden Technologies Inc. | Hisense | 1.0 hp Air Conditioner (Inverter) | AS-09TR2S | 2.64 | 815 | 110.03 | 4.39 | 5 | R410a | 2088 | https://pelp.doe.gov.ph/vapproved.php?7V1UvW5kME5CgXvW9Weld2VLURNVVRWSWpeUzZ5U3dvTXZdUGL3nWWT0 |
| 193 | Finden Technologies Inc. | Hisense | 2.0 hp Air Conditioner (Inverter) | AS-18TRSr | 5.2 | 1835 | 247.73 | 4.5 | 5 | R32 | 675 | https://pelp.doe.gov.ph/vapproved.php?d1V1u4rQ4RHk4N4eXUeGU5akdBM0Z5NXVuzTZ6anVBuS85VndZTYVQTO |
| 194 | Concepcion Midea Inc. | Midea | Window Inverter | FP-51ARA025HEIV-N4 | 6.01 | 2010 | 271.35 | 4.1 | 5 | R410a | 2088 | https://pelp.doe.gov.ph/vapproved.php?a6NSR3jBRWgQzmVYYvQk6FNGNHVUxY1pLd2gDY0KX3VBWEx4mZwST0 |
| 195 | Concepcion Midea Inc. | Midea | Window Inverter | FP-51ARA020HEIV-N4 | 5.28 | 1765 | 238.28 | 4.1 | 5 | R410a | 2088 | https://pelp.doe.gov.ph/vapproved.php?7RW83Z3nRzRnqTWxvWEVaeFsvGhaQil3SFNIkNqUS94c1VrbDZ1OG1SUTO |
| 196 | AHAM CORPORATION | AMERICAN HOME | AIR CONDITIONER | AHAC-MST20DC0900 | 2.64 | 940 | 126.9 | 3.11 | 1 | R32 | 675 | https://pelp.doe.gov.ph/vapproved.php?NidLMzbWMOntK3VwRnFFOHFVDFSD04OH4dSmKFTBicFInZ0ua0 |
| 197 | JOHNSON CONTROLS-HITACHI AIR CONDITIONING PHILIPPINES, INC. | Hitachi | Air Conditioner | RA-06SR | 1.78 | 577 | 124.63 | 3.32 | 2 | R410a | 2088 | https://pelp.doe.gov.ph/vapproved.php?7TW9KRWvRdLUJspTBok1VmvGpZzF2Hn2pJcm1v8TYWWh5T3EKzL8pZ0 |
| 198 | JOHNSON CONTROLS-HITACHI AIR CONDITIONING PHILIPPINES, INC. | Hitachi | Air Conditioner | RA-10SR | 2.69 | 898 | 193.97 | 3.08 | 1 | R410a | 2088 | https://pelp.doe.gov.ph/vapproved.php?7b2hTmkaXc4N1BDSmpERW1k5WfUzXBGKzFOUWJbWfJ6cVfma9BWXVDRTO |
| 199 | JOHNSON CONTROLS-HITACHI AIR CONDITIONING PHILIPPINES, INC. | Hitachi | Air Conditioner | RA-08SR | 2.44 | 752 | 162.43 | 3.2 | 1 | R410a | 2088 | https://pelp.doe.gov.ph/vapproved.php?7RncycZ8TnFN01D4xJ5bYFNJQJNHNVWUJLUpIRUMYnBkaWVVOVTO |
| 200 | JOHNSON CONTROLS-HITACHI AIR CONDITIONING PHILIPPINES, INC. | Hitachi | Air Conditioner | RA-15SR | 3.56 | 1143 | 246.89 | 3.43 | 3 | R410a | 2088 | https://pelp.doe.gov.ph/vapproved.php?7DhZUNCL2haXJp4LJwWUJXMDVNR1UWVHYRZMSSGZFSnNaOVJVVXESVTO |
| 201 | JOHNSON CONTROLS-HITACHI AIR CONDITIONING PHILIPPINES, INC. | Hitachi | Air Conditioner | RA-20SR | 5.31 | 1910 | 412.56 | 2.9 | 1 | R410a | 2088 | https://pelp.doe.gov.ph/vapproved.php?71NEdTNnRNwNtFsd1tqTEc1L253aDMwZINUZG1NeURDQClwaF5WVnZTO |
| 202 | JOHNSON CONTROLS-HITACHI AIR CONDITIONING PHILIPPINES, INC. | Hitachi | Air Conditioner | RA-08HVQC | 2.44 | 884 | 119.34 | 3.8 | 4 | R410a | 2088 | https://pelp.doe.gov.ph/vapproved.php?7WGoSEnqNIVsRnBUZrQXNzUKQYr2REaWJDR4hmEExwEaDz2ZorNRVtd0 |
| 203 | JOHNSON CONTROLS-HITACHI AIR CONDITIONING PHILIPPINES, INC. | Hitachi | Air Conditioner | RA-10HVQC | 2.81 | 1436 | 193.86 | 3.8 | 4 | R410a | 2088 | https://pelp.doe.gov.ph/vapproved.php?eHLEEnzEcdFz3bmNuYkpTMR1azE2MGkwSTRHNUGrFNMV3p6N0Ndo0 |
| 204 | JOHNSON CONTROLS-HITACHI AIR CONDITIONING PHILIPPINES, INC. | Hitachi | Air Conditioner | RA-06HSVC | 1.94 | 782 | 105.57 | 3.56 | 3 | R410a | 2088 | https://pelp.doe.gov.ph/vapproved.php?7EowT5eRthvUJNGa14dLUUvZVQvSUZz2M6M4F4MSFKWEM3wFFTRVco0 |
| 205 | JOHNSON CONTROLS-HITACHI AIR CONDITIONING PHILIPPINES, INC. | Hitachi | Air Conditioner | RA-08HSVC | 2.44 | 1139 | 153.77 | 3.56 | 3 | R410a | 2088 | https://pelp.doe.gov.ph/vapproved.php?7eEaMzYbYn2wPdcJuzWYRkxKQZVQc1NMbVpYcmVJN2JwbE4amZcOD0 |
| 206 | JOHNSON CONTROLS-HITACHI AIR CONDITIONING PHILIPPINES, INC. | Hitachi | Air Conditioner | RA-10HSVC | 2.81 | 1367 | 184.55 | 3.8 | 4 | R410a | 2088 | https://pelp.doe.gov.ph/vapproved.php?7TrROWHNDMw9F5mFhNzYTrnNuZvFGB0Vng1NUSFd43N0Gau6a0hKWTO |
| 207 | Haier Electrical Appliances Philippines Inc. | Haier | Air Conditioner | HSU-19QSV32 | 5.28 | 1760 | 237.6 | 4.8 | 5 | R32 | 675 | https://pelp.doe.gov.ph/vapproved.php?7TtUyVNSGRtKZkNvvaWVnVVGqM5NOVnkVXEWXMAySUI1WdtdBFH0Z0 |
| 208 | Haier Electrical Appliances Philippines Inc. | Haier | Air Conditioner | HSU-19PSV32 | 5.28 | 1760 | 237.6 | 4.58 | 5 | R32 | 675 | https://pelp.doe.gov.ph/vapproved.php?7RnKQkVTK3Nz2zrNW43b2kbbk0VDKkE00RF4YSDMkSmhOWIwVgzto0 |
| 209 | Haier Electrical Appliances Philippines Inc. | Haier | Air Conditioner | HSU-25QSV32 | 6.67 | 1999.2 | 269.89 | 5.54 | 5 | R32 | 675 | https://pelp.doe.gov.ph/vapproved.php?7a0sQVNWmYvNEFqEVOCHbyZW9Q1DU1VOMnUxRT0xUGJst1pHRTdtd0 |
| 210 | Haier Electrical Appliances Philippines Inc. | Haier | Air Conditioner | HSU-25PSV32 | 6.67 | 1999.2 | 269.89 | 5.54 | 5 | R32 | 675 | https://pelp.doe.gov.ph/vapproved.php?7dGqUVEbYRzhEJbaGNQeikM4rNsem9eUfHMZKh0005d2bcFZjRHGOTO |
| 211 | JOHNSON CONTROLS-HITACHI AIR CONDITIONING PHILIPPINES, INC. | Hitachi | Air Conditioner Rev. 1 | RA-08HV | 2.5 | 621 | 83.84 | 5.15 | 5 | R410a | 2088 | https://pelp.doe.gov.ph/vapproved.php?7TkwSUpTn6LMDhMWR5RTk4ZT1kxJPvMvON1pXNhticQCMUuQVFRTO |
| 212 | JOHNSON CONTROLS-HITACHI AIR CONDITIONING PHILIPPINES, INC. | Hitachi | Air Conditioner Rev. 1 | RA-10HV | 2.94 | 785 | 105.98 | 4.65 | 5 | R410a | 2088 | https://pelp.doe.gov.ph/vapproved.php?7SXJndvQVIM49YQVRIldDdFTENRanJndFhxbVITM2btvFGK1dubXZico0 |
| 213 | JOHNSON CONTROLS-HITACHI AIR CONDITIONING PHILIPPINES, INC. | Hitachi | Air Conditioner Rev. 1 | RA-15HV | 3.61 | 1048 | 141.48 | 4.15 | 5 | R410a | 2088 | https://pelp.doe.gov.ph/vapproved.php?7QWLVWv0FEWUlvYq6NS4ZrhEQVieFBwVfNac29VT3k8FluERiST0 |