

MEMORANDUM

TO

AFFECTED DISTRIBUTION UTILITIES

AFFECTED GENERATION COMPANIES

NATIONAL GRID CORPORATION OF THE PHILIPPINES

(NGCP)

FROM

.

UNDERSECRETARY EMMANUEL P. JUANEZA

SUBJECT

ADVISORY ON ALL AFFECTED POWER SECTOR STAKEHOLDERS TO IMMEDIATELY INSPECT, ASSESS AND REPORT ANY DAMAGE CAUSED BY THE 6.6

MAGNITUDE EARTHQUAKE ON 24 JULY 2021

DATE

JUL 30 2021

This refers to the Earthquake Information No. 2 of the Philippine Institute of Volcanology and Seismology on the occurrence of a 6.6 magnitude earthquake on 24 July 2021 (Saturday) at 04:48 AM with epicenter located at 13.65N, 120.54E - 023 km S 26° W of Calatagan, Batangas. The report includes the following intensity on the following areas:

- Intensity V Calapan City & Puerto Galera, Oriental Mindoro; Sablayan and Magsaysay, Occidental Mindoro; Carmona & Dasmarinas City, Cavite
- Intensity IV Quezon City; Marikina City; Manila City; Makati City; Taguig City;
 Valenzuela City; Pasay City; Tagaytay City, Cavite; Batangas City
 & Talisay City, Batangas; San Mateo, Rizal
- Intensity III Pasig City; San Jose del Monte City, Bulacan

In line with Section 37, Chapter III of Republic Act No. 9136, also known as the Electric Power Industry Reform Act of 2001, which mandates the Department of Energy (DOE) to supervise the restructuring of the electric power industry to ensure reliability, quality, and security of electric power supply, the DOE hereby issues this advisory directing all power sector stakeholders to immediately inspect, assess and report any damage/s incurred by the facilities caused by the said earthquake.

Pursuant to the directive of Secretary Alfonso G. Cusi, all reports on the assessment and inspection should be submitted to the Task Force on Energy Resiliency (TFER) and the Electric Power Industry Management Bureau (EPIMB), as lead and co-lead group in the DOE, respectively, as they are handling the monitoring of calamity-related concerns on the Electric Power Industry. The TFER and EPIMB will be coordinating with the concerned stakeholders to ensure the normal operations of affected power stakeholders after the occurrence of this natural calamity. All reports can be submitted to tfer.secretariat@gmail.com and mcmarasigan.epimb@gmail.com.

For compliance.

EMMANUEL P. JUANEZA

Undersecretary